School Name:	Atholton Elementary
IEQ Team Leader: Melani	e Secula
LOOK-FORS	ROOM/LOCATION
1. No unusual or offensive odors, or temperature discomfort	Portable #107, Room 131
2. No Air Fresheners	Rm 207, #125
3. No food, dirty lunch boxes, etc. left in room	
4. Vents are clean and unobstructed	Rm 118, café, 131, 105, elevator room,
5. Temperature sensors are not blocked	
6. Area appears clean and dust free	Rm 121, 119, 208, 102
7. No signs of animal infestation	

School Name:	Atholton Elementary
IEQ Team Leader: Melani	e Secula
8. Ceiling tiles present; no broken, stained, or painted	Rm 201, 213, 210, 121, 207, 119, 117, 209, stage, café, hallway, 130, upstairs storage- girls bathroom, 102, PE closet & office, 105, 103, front storage, 133, 109, 102, 126, health,
9. Walls show no signs of water damage/mildew/ paint irregularities	Rm 209,
10. No condensation or other evidence of humidity on ceilings, walls, doors, etc.	
11. Limited use of non-issued HCPSS furniture and appliances	Rm 121, 119, 114(media office), mailroom
12. No excessive fabric materials, stuffed animals, beanbags, pillows, etc.	
13. No structural or physical gaps around exit doors	Rm119/121, hallway exit to outside by stage, mechanical room door exit to outside,
14. No improperly stored materials/chemicals	Rm 211, 209, 121, 208, 102, 119, 133
15. Floor coverings are level and secure (tile, carpets, wood board, etc.)	Rm 107,

School Name:	Atholton Elementary
IEQ Team Leader: Melani	e Secula
16. Barrier mats vacuumed well	
17. Fish tanks are clean and located away from vents/thermostats	
18. Waterproof barriers in place for plants and no standing water	
19. Sinks and fountains drain quickly and work properly including absence of leaks	Rm 202, front office bathroom, 101, 119, first floor boys bathroom,
20. No standing water in sinks, fountains, on counter	
21. Carpet dry nearby sinks, fountains	
22. Soap and paper towels available	
23. All electrical outlets secure, no frayed wires on equipment	
24. All electrical cords secured and not extending across walkways	
25. No extension cords used as permanent wiring	

School Name:	Atholton Elementary
IEQ Team Leader: Melani	e Secula
26. No electrical equipment near sinks or source of water	
27. No exposed disconnected wires	
ADJACENT SCH	OOL GROUNDS
LOOK-FORS	ROOM/LOCATION
28. No litter	
29. No large insect populations (wasps, bees)	
30. Awnings secure, no leaks	
31. Shrubbery not near vents or windows which can be opened	
32. Trees do not provide access to roof	
33. No broken windows	
34. Windows are closed	
35. Exterior doors are closed	
36. No pools of standing/stagnant water	

School Name:	Atholton Elementary				
IEQ Team Leader: Melanie Secula					
37. Exterior veneer intact					
38. Outside lights working and intact					
39. Gutters and downspouts clear/working					
40. No stains from roof on outside walls					
41. Bins from garbage and recycling clearly marked					
42. Hard surfaces (sidewalks, etc.) cleared of any turf application					
43. Proper maintenance of planted beds and other vegetation					
44. Landscaping and turf look healthy and disease free					
COMMENTS:					

IEQ SCHOOL DATA BASE		
Principal: Shawna Holden		
IEQ System Leader: Greg Maciulla		
COMMENTS	ADMIN	
Room Portable #107-Pungent Odor / #131-Cold Temperature		
Room #207-candle(not lit) / #125-air spray	yes	
Room #118- heater vent sort of blocked by supply cart / #cafe-vent bent / #131-move items from on top of heater / #105-broken return vent / #elevator room-vant dirty /		
Room #121-cobwebs over window & sink is dirty / #119-some cobwebs over window / #208 cobweb behind door / #102 ceiling & vents needs dusting / #102 cabinet under sink needs to be wiped out	yes	

IEQ SCHOOL DATA BASE	
Principal: Shawna Holden	
IEQ System Leader: Greg Maciulla	
Room #201 - ceiling tile propped up w/pencil (sprinkler), also chipped ceiling tile, also black mark on tile, and dirty tile / #213-tile not laying flat / #210 - broken tile by sprinkler / #121 - broken tile / #207 - watermarks on several tiles(5) & cracked tile / #119 watermark & hole in ceiling tiles / #117 - 3 ceiling tiles with watermarks, one dirty tile / #209-replace tile around sprinkler head, dirty ceiling tile / #Stage - ceiling tiles need replaced(bowed) / #Cafe-ceiling tiles need swept & some are bowed / #hallway-outside of cafe near water fountain- stained ceiling tile / #130- 2 stained tiles / #upstairs storage-ceiling tiles stained / #102 stained/broken tile / #PE Closet & Office-stained/broken tile / #105-stained/broken tile / #103-stained tile / #front storage-tile stain / #133(media)-stained ceiling tiles by fire alarm & torn tile by front screen / #109-stained tiles / #102-stained tile / #126 stained tile / #health-hole in tile in back closet /	yes
	yes
Room #200 broken concrete well tile (lump) /	
Room #209 - broken concrete wall tile (lump) /	
Room #121-preschool fridge and microwave / #119-preschool fridge and microwave / #114- refrigerator / #mailroom-refrigerator & microwave	yes
Room #119/121-gap in door to outside / hallway exit to outside by stage-need seal to close gaps / mechanical room exit to outside-need door sealed to close gaps /	
Room #211-nail polish remover under sink / #209-nail polish remover under sink / #121 cleaners(bleach, borax, goo gone) under sink(preschool) / #208-clorox spray cleaner under sink / #208-mouse traps under sink / #102 cleaning supplies under sink / #119-bleach & goo gone under sink(preschool) / #133-clorox /	yes

Room #107-door and floor outside classroom show signs of water infiltration /

IEQ SCHOOL DATA BASE		
Principal: Shawna Holden		
IEQ System Leader: Greg Maciulla		
Rm #202 - sink leaking & rust present / #front office bathroom-sink leaking or just stained		
Rm #202 - sink leaking & rust present / #front office bathroom-sink leaking or just stained from prior leak? / #101-calcium on pipes under sink / #119-calcium on pipes under sink / #first floor boys bathroom-urinal leaking /		

IEQ SCHOOL DATA BASE		
Principal: Shawna Holden		
IEQ System Leader: Greg Maciulla		
COMMENTS	ADMIN	

IEQ SCHOOL DATA BASE			
Principal: Shaw	na Holden		
IEQ System Leader: Greg	Maciulla		

DATE: 11/28/16					
FACILITIES	WORK ORDER NUMBER of POTENTIAL IEQ	DATE ASSIGNED	COMPLETION DATE	30 DAY REVISIT	CLOSED
yes	13564 & duplicate of 16574	12/1/16	12/6/16		
	N/A				
yes			completed in December		
	N/A				

DATE	C: 11/28/16			
	17698, 17850, 16671,17701,190		Work Order #15866 Completed	
		entered in school dude on	12/23/16	
yes	19617	1/31/17		
	N/A			
yes		entered in school dude on 1/31/17		
	N/A			
yes		entered in school dude on 1/31/17		

DATE				
yes	19645			

DATE	2: 11/28/16				
FACILITIES	COMMENTS/W ORK ORDER	ASSIGNED TO	COMPLETION DATE	30 DAY REVISIT	CLOSED

DATH	DATE: 11/28/16				